	er ID 54821 2009 1:28:22 PM									Page
Revision ID: Item Name:	D3780-041 Armrest Assembly 1/05/10 Start Qty: 2.00 1/15/10 Req'd Qty: 2.00		Accept	Cust Item 1				Setup Sta		
Approvals:	Process Plan: CL QC:	Date: 09/12/23	SPC (Y/N):		ate:		I	Run Sta Sto	1 8 8 8	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Draw Number	Draw	Plan	Accept	Reject	Reject	Insp.
Draw Nbr	Revision Nbr		Run Hours	Number	Rev.	Code	Qty	Qty	Number	Stamp
D3780	Rev D									
Small Fab	Small Fab Memo 1- assemble ****torque	as per dwg D3780 screws as per dwg D3780**	0.00			,	Es.	03/03/	chi (2
110 QC Quality Control	QC5-Inspect part comp was wating of Memo		0.00	03 /17			(3)			
120 Packaging Packaging	Identify as per dwg & Si	ock Location: 26/	0.00			1	King	13/17	(2)

7

.

W/O:		d	WO	RK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHAN		Ву	8	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
									, , , , , , , , , , , , , , , , , , , ,	
						+				
Part No		PAR #:								
	Reso	lution:	Disposition	:	_ QA: N/0	Clo	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)				
		Description of NC		Corrective Action Sec	tion B		Verifica	ation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	Section		Chief Eng	QC Inspecto
						E-4				

	er ID 54821 009 1:28:22 PM								Page 2
Item ID: Revision ID: Item Name: Start Date: Required Date: Reference:	D3780-041 Armrest Assembly 1/05/10 Start Qty: 2.00 1/15/10 Req'd Qty: 2.00		Accept	Cust Item Customer:	ID:			Start Stop	
Approvals:	Process Plan: QC:	Date:	Tooling: SPC (Y/N):		ate:		9	Start Stop	
Sequence ID/ Work Center ID 130 QC Quality Control	Operation Description QC21- Final Inspection -	Work Order Release	Set Up/ Run Hours 0.00	Draw Number	Draw Rev.	Plan Code	Accept Qty	t R	eject Insp. umber Stamp

MF 10-3-17

Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:			WC	RK ORDER CHANG	GES					
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Tev										
Part No		PAR #:	Fault Cate	gory:	NCR	: Yes	No DQ	A:	_ Date: _	
4.	R	esolution:	Disposition	n:	QA:	N/C CIG	sed:		Date:	
NCR:			WORK ORDI	ER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC			ction B		Verifi	cation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Chief Eng	QC Inspector
									/	
	*									1

December 22, 2009 1:28:11 PM

Work Order ID: 54821

Parent Item: D3780-041

Parent Item Name: Armrest Assembly

Comments:



Start Date: 1/05/10

Required Date: 1/15/10

Page 1

Component Item ID/	Replacement	Me-/	-	E INS					Start Qty: 2.00		Required Qty: 2	.00
D3696-041	Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date	Status
Arm Assembly D3781-041		Manufactured	No			3548	Each (2)	0.0000	2.0000	Bo/	Issued	
Lateral Cushion Assembly		Manufactured	No			100	Each	1.0000	2.0000	510	63/11	
				Warehous Locati Main Ware	on	Loc Q	t <u>v</u>	Loc Code	1/2	55	171 @	9
D3781-043 Armrest Cushion Assembly		Manufactured	No	ST 4	7992	100	I I Each		2.0000	Kal	63/	
				Warehouse Locatio Main Wareh	<u>on</u>	Loc Qt	Σ <u>Ι</u>	oc Code	51716		B5665	020
D3785-3 Bracket		Manufactured	No	48	8436 B S	100			2.0000	50/	03/4	

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	es No I	DQA:	Date:	
		esolution:							
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (N	CR)			
DATE	OTED	Description of NC			ion B	Ve	rification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		nn 0	Section C	Chief Eng	QC Inspector
		*,							

December 22, 2009 1:28:11 PM

Page 2

Work Order ID: 54821

Comments:

Parent Item: D3780-041

Parent Item Name: Armrest Assembly



Start Date: 1/05/10

Required Date: 1/15/10

Component Item ID/ Item Name	Replacement	Mfg/	Bin	Primary					Start Qty: 2.00		Required Qty:	The state of the s
D3977-1	Item ID	Purch		Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty	Date	Status
	III (88)	Manufactured	No			100	Each	VI		Issued	Issued	Status
							Lacii	1.0000	2.0000	11		

Warehouse Loc Oty Loc Code Location Main Warehouse ST

D3978-1 Nut	Manufactured	No	51701	100	1 Each	1.0000	2.0000	



Warehouse Location Main Warehouse ST139 51702 100 Each

D.	3979	9-1				
				III		
W	ash	er			-	

Manufactured

6.0000

2.0000

Warehouse Location	Loc Qty	Loc Code
Main Warehouse		
ST	6	
51703	6	

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	ES						
DATE	STEP	PR	OCEDURE CHAP	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	_ Date: _			
Resolution:			Disposition	Disposition: QA: N/C CI				closed: Date:			
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	1)					
DATE	CTED	Description of NC		on B	Verificati			Approval			
DATE	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Approval Chief Eng	QC Inspector			
						3					
								8			

December 22, 2009 1:28:12 PM

Page 3

Status

Work Order ID: 54821

Parent Item: D3780-041

Parent Item Name: Armrest Assembly

Comments:



Start	Date:	1/05/10

Required Date: 1/15/10

Component Item ID/	Replacement	Mfg/	Bin	Dut				3	Start Qty: 2.00		Required Qty: 2	2.00
Item Name	Item ID	Purch	Item		Last Location	Route Unit of Seq ID Measur		Qty on Hand			Oty Date	84
AN960JD10L	THE STATE OF THE S	Purchased	No					Hanu	Qty To Pick	Issued	Issued	34
						100	Each	5,085.000	4.0000			

65I 017

NAS 1149203327 M112794 (40)

AN970-6

Purchased

Warehouse Location Main Warehouse ST 101291 104885 105793 109632 110985

No

Loc Qty Loc Code 5085 16 153 236 190 4490 100 Each

44.0000 4.0000

Loc Code

Loc Qty
Lot Oty
44
8
36

Dart Aerospace Ltd WORK ORDER CHANGES W/O: Approval Approval DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: ____ Fault Category: ______ NCR: Yes No DQA: ____ Date: _____ Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: _____ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B Verification Description of NC Approval Approval STEP DATE Sign & **Action Description** Initial QC Inspector Section A Chief Eng Section C Date Chief Eng Chief Eng

December 22, 2009 1:28:12 PM

Work Order ID: 54821

Parent Item:

D3780-041

Parent Item Name: Armrest Assembly

Comments:

Start Date: 1/05/10 Start Qty: 2.00

Required Date: 1/15/10 Required Qty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Primary Purch Item Location

No

Purchased

Last Location

Route Seq ID

Unit of Measure

Each

Qty on Hand

Remaining Qty Qty To Pick Issued

Date Issued

Status

Page 4

MS21042L3

Warehouse Loc Oty Loc Code

100

Location Main Warehouse

ST

110844 111274 111668 112314

2,372.000 4.0000

MS24665-302

Purchased

No

112385 500 100 Each 20.0000 2.0000

Warehouse Loc Qty Location

Main Warehouse

111359

ST

20

20

Loc Code

Dart Aerospace Ltd WORK ORDER CHANGES W/O: Approval Chief Eng / Approval DATE STEP PROCEDURE CHANGE By Date Qtv QC Inspector Prod Mar Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

22/25/2007		Description of NC Corrective Action Section B					//	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
	=							
								e:

December 22, 2009 1:28:15 PM

Work Order ID: 54821

Parent Item:

D3780-041

Parent Item Name: Armrest Assembly

Comments:

Component Item ID	/
Item Name	9.7

Replacement Mfg/ Item ID Purch

MS24693-C272 Purchased

Screw

MS24693-C277 Purchased



Primary
Location

No

No

Warehouse

Location Main Warehouse ST

109297

Last Location

Route Seq ID 100

Unit of Measure Each

Qty on Hand

Remaining Qty To Pick Issued 1,432.000 4.0000

Start Qty: 2.00

Start Date: 1/05/10

Qty

Date Issued

Required Date: 1/15/10

Required Qty: 2.00

Status

Page 5

Warehouse Loc Oty Loc O	Code
Main Warehouse	
ST 1432	
17137 17831 8814 8815 9063 9370	
100 Each 16.00	00 4.000

Loc Qty

16

16

4.0000

Loc Code

Dail Ac	rospace Lt	a .								<u> </u>
W/O:			W	ORK ORDER CH	ANGES					
DATE	STEP	PR	OCEDURE CHA	CEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
Part No	:	PAR #:	Fault Cate	egory:	NC	R: Yes	No DQ	A:	Date:	
	Reso	lution:	Disposition	on:	QA	: N/C C	losed:		Date: _	
NCR:			WORK ORD	ER NON-CONFO	RMANCE	(NC	₹)			
		Description of NC	Corrective Action		Section B	Verifica		ation	an Annewal	A
DATE	STEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign Date	& Secti		Approval Chief Eng	Approva QC Inspect

December 22, 2009 1:28:16 PM

Work Order ID: 54821

Parent Item:

D3780-041

Parent Item Name: Armrest Assembly

Comments:

Component Item ID/ Item Name

Replacement Mfg/ Item ID Purch

NAS1149D0663J Purchased



Warehouse

Start Date: 1/05/10

Start Qty: 2.00

Required Date: 1/15/10

Page 6


Required Qty: 2.00

Primary Bin Last Route Unit of Item Location Qty on Remaining Location Qty Seq ID Measure Date Hand Qty To Pick Status Issued No Issued 100 Each 195.0000 2.0000


> Loc Oty Loc Code

Location Main Warehouse ST 195 112612 195

Dart Aerospace Ltd W/O: WORK ORDER CHANGES Approval Approval DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: ____ WORK ORDER NON-CONFORMANCE (NCR) NCR: Corrective Action Section B Description of NC Verification Approval Approval DATE STEP Sign & **Action Description** Initial Section A QC Inspector Section C Chief Eng Date Chief Eng Chief Eng



		•	*



				(4) •:

